### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009677 Address: 333 Burma Road **Date Inspected:** 20-Sep-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** ZPMC and ABF **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

**Bridge No:** 34-0006 **Component: SAS** Tower

## **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Mr. Wai Pau, was present during the times noted above for observations relative to the work being performed.

#### Bay #11 East and West Tower Shop

East tower lift 3:- Caltrans QA inspector observed ten ZPMC welders performed FCAW process on CJP welds of corner diagonal stiffener plates of skin plates C to D and B to C. The locations of corner diagonal stiffener plates are from 82.25m to 111.67m. The FCAW process were monitored and recorded by ZPMC and ABF QC inspector. Based on Caltrans QA Inspector observations, no discrepancies were noted.

West tower lift 3:- Caltrans QA inspector observed five ZPMC welders installed corner diagonal stiffeners on the skin plates B to C. The locations for installing corner diagonal stiffeners are from 82.25m to 111.67m. The SMAW tack welding has been applied on the corner diagonal stiffener joints after the fit up accepted by ZPMC and ABF QC. Based on Caltrans QAI observations, no discrepancies were noted.

East and west tower lift #3 interior split plates: - Caltrans QA inspector performed final VT and dry MT inspection on interior split plate welds for skin plate A, C and D of east and west tower lift #3. The weld ID number is ESD1-SPSA3-3-1A/B~4A/B, ESD1-SPSA3-56-1A/B~4A/B, WSD1-SPSA3-67-1A/B~4A/B and WSD1-SPSA3-56-1A/B~4A/B. The welds for VT and MT inspection have been accepted by ZPMC prior Caltrans QA inspection Base on Caltrans inspection, the welds appeared to be in compliance with requirements of AWS D1. 5 2002 and Caltrans contract documents.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# **Summary of Conversations:**

As notes within report above.

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinoved 13482570045, who represents the Office of Structural Materials for your project.

Inspected By:	Pau,Wai	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer